Transmittal Letter



	acon 48150 IC COPIES TO chlaufman (EGLE on (Ford)	FROM Kristoffer Hinskey 248-994-2240 kristoffer.hinskey@arcadis.com DATE October 4, 2022			
PROJECT N 30146655	UMBER	SUBJECT Operation, Monitoring, and Maintenance (OM&M) Field Notes – 34600 Beacon			
We are se	ending you:				
Copies	Delivery Date	Description			
1	10/6/2022	Operation, monitoring, and maintenance field notes.			
☐ AN Ap	oproved oproved as Noted s Requested	□ CR Correct and Resubmit □ Resubmit Copies □ F File □ Return Copies □ FA For Approval □ Review and Comment			
Mailing M	ethod				
 U.S. Postal Service 1st Class □ Courier/Hand Delivery □ FedEx Priority Overnight □ FedEx 2-Day Delivery □ Certified/Registered Mail □ United Parcel Service (UPS) □ FedEx Standard Overnight □ FedEx Economy □ Other: Email 					
Comment	s:				
field note	s. These field not	reemptive mitigation (IPM) system Operation, Monitoring, and Maintenance (OM&M) es were recorded during OM&M visits at the property between March 31, 2020 and t me know if you have any questions.			

Created	2020-12-04 18:58:52 UTC by Emma Witherspoon
Updated	2020-12-04 19:39:44 UTC by Emma Witherspoon
General Information	
System Inspector	Emma Witherspoon
Date	2020-12-04
Time	13:58
System Details Link	34600 Beacon
Property Address	34600 Beacon
Check Inspection(s) to be Completed	Full System Inspection
Get weather data from National Weather Service Website for your current location?	N/A
Weather	Cloudy
Ambient Temperature	44.06
Barometric Pressure	29.85
Indoor Temperature	70
Design Components	
Does the house have a basement?	Yes
Does the house have a sump?	Yes
Does the house have garage retrocoat?	Yes
Does the house have shed retrocoat?	No
Does the house have basement retrocoat?	Yes
Does the house have a crawlspace barrier?	No
Does the house have an inaccessible crawlspace?	No
Does the house have a water sensor?	No
System Inspection	
Fan	
Fan(s) operating?	Yes
Are there any unusual fan noises?	No

Piping	
s any caulking required around pipe penetrations, slab cracks, expansion joints, or foundation walls?	No
Are piping, piping joints, and brackets intact and secure?	Yes
s the insulation and insulation jacket damaged or missing in garage or exterior piping?	No

vaives				
Upon arrival, are all valves in the same position as	Yes			
the prior visit (reference Power BI)?				

Drains

Do any drain seals need to be repaired or replaced?	No
Basement	
Is water present in the basement?	No
Sumps	
Is the sump full/evidence pump is broken?	No
Was the owner notified?	Yes
Sump Comments	Sump is in good condition
Garage Retrocoat	
Is retrocoat damaged or missing?	No
Basement Retrocoat	
Is retrocoat damaged or missing?	No
Labels	
Are labels present at the pipe, control panel, utube, and breaker?	Yes
Are labels present at the sump?	Yes



Sump Label Photos

Basement Retrocoat Label Photos



Are labels present at the garage retrocoat?

Yes

Garage Retrocoat Label Photos



	V.
Is the u-tube accurate (test with micromanometer/manometer, rezero/replace as	Yes
needed)?	
Is the vacuum switch accurate (test with micromanometer)?	Yes
Do any monitoring points (MP/SSMP) need to be repaired or replaced?	No
If multiple systems are present, were both inspected?	N/A
Inspection Measurements	
Pre-Measurement Conditions	
Are vacuum readings being taken under closed building conditions?	Yes
Do any monitoring points have transmitters?	No
Measurements and Valve Positions	
ineasurements and valve rositions	
U-Tube Manometer, 14:28, -0.2	
Vacuum ID Link	34600 Beacon, U-Tube Manometer
Vacuum ID	U-Tube Manometer
Date	2020-12-04
Time	14:28
Vacuum Reading (in. w.c.)	-0.2
Number Vacuum Reading	-0.2
BV-1, 14:16, 50	
Valve ID Link	34600 Beacon, BV-1
Valve ID	BV-1
Date	2020-12-04
Time	14:16
Valve Position at Arrival (% Open)	50
Valve Position at Departure (% Open)	50
BV-2, 14:26, 50	
Valve ID Link	34600 Beacon, BV-2
Valve ID	BV-2
Date	2020-12-04
Time	14:26
Valve Position at Arrival (% Open)	50
Valve Position at Departure (% Open)	50
Were interim vacuum readings taken between initial and final vacuum readings?	No
Inspection Reading Analysis	
Manometer	
Is the system manometer steady?	Yes

SSMP/MPs	
Were any vacuum monitoring points not accessible? Please specify.	SSMPs were not sampled
Do all vacuum monitoring points meet -0.02 in w.c. threshold?	Yes
Were any ball valve positions changed?	No
Alarm Testing	
Sensaphone Link	N/A
Does the vacuum switch alarm work? Test the alarm condition and verify an alarm registers.	Yes
Does the fan disconnect alarm work? Test the alarm condition and verify an alarm registers.	Yes
Does the transmitter alarm work? Test the alarm condition and verify an alarm registers.	N/A
Check the alarm history on the disconnect for the fan. Was it off for any length of time?	No
Is the cloud logging vacuum readings properly (log in to check)?	N/A
Repairs	
Sample Delay	
Send Sample Delay Email	N/A
email body	
Repair Completion	
Were seam repairs completed during this visit?	No
Were system repairs completed during this visit?	No
Are there outstanding repairs to be completed?	No
Owner/Tenant Observations	
Have there been any changes to the fan noise level or vibration?	No
Have any structures been built or modified that require vapor mitigation?	No
Engineer Notification	
Send Inspection Completion Email	N/A
email body	
Engineer Notification	
Send Inspection Completion Email - add any repairs, repair needs, or critical communications in email text	N/A

email body

Created	2021-02-18 20:07:51 UTC by Seth Turner
Updated	2021-02-18 21:46:20 UTC by Andrew Banitt
General Information	
System Inspector	Seth Turner
Date	2021-02-18
Time	16:00
System Details Link	34600 Beacon
Property Address	34600 Beacon
Check Inspection(s) to be Completed	Full System Inspection
Get weather data from National Weather Service Website for your current location?	N/A
Weather	18F, cloudy
Ambient Temperature	18F
Barometric Pressure	30.21
Indoor Temperature	70
Design Components	
Does the house have a basement?	Yes
Does the house have a sump?	Yes
Does the house have garage retrocoat?	Yes
Does the house have shed retrocoat?	No
Does the house have basement retrocoat?	Yes
Does the house have a crawlspace barrier?	No
Does the house have an inaccessible crawlspace?	No
Does the house have a water sensor?	No
System Inspection	
Fan	
Fan(s) operating?	Yes
Are there any unusual fan noises?	No
Piping	
Is any caulking required around pipe penetrations,	No
slab cracks, expansion joints, or foundation walls?	
Are piping, piping joints, and brackets intact and secure?	Yes
ls the insulation and insulation jacket damaged or missing in garage or exterior piping?	No
Valves	
Upon arrival, are all valves in the same position as	Yes

the prior visit (reference Power BI)?

Drains

Do any drain seals need to be repaired or replaced?	No

Basement

Is water present in the basement?

Sumps

Is the sump full/evidence pump is broken?

No

Was the owner notified?

No

Garage Retrocoat

Is retrocoat damaged or missing?

Basement Retrocoat

Is retrocoat damaged or missing?

Labels

Are labels present at the pipe, control panel, utube, and breaker?

Yes

Common Label Photos



Are labels present at the sump?

Yes

Sump Label Photos



Are labels present at the basement retrocoat?

Yes

Basement Retrocoat Label Photos





Vacuum	Μo	nito	oring
--------	----	------	-------

Yes
Yes
No
N/A

Inspection Measurements

Pre-Measurement Conditions

Are vacuum readings being taken under closed	Yes
building conditions?	
Do any monitoring points have transmitters?	No

Measurements and Valve Positions

U-Tube Manometer, 16:05, -0.036

Vacuum ID Link	34600 Beacon, U-Tube Manometer
Vacuum ID	U-Tube Manometer
Date	2021-02-18
Time	16:05
Vacuum Reading (in. w.c.)	-0.036

SSMP-1, 16:13, -0.006

Vacuum ID Link	34600 Beacon, SSMP-1
Vacuum ID	SSMP-1
Date	2021-02-18
Time	16:13
Vacuum Reading (in. w.c.)	-0.006
Number Vacuum Reading	-0.006

SSMP-1, 16:28, -0.005

Vacuum ID Link	34600 Beacon, SSMP-1
Vacuum ID	SSMP-1
Date	2021-02-18
Time	16:28
Vacuum Reading (in. w.c.)	-0.005
Number Vacuum Reading	-0.005

U-Tube Manometer, 16:28, -0.037

Vacuum ID Link	34600 Beacon, U-Tube Manometer
Vacuum ID	U-Tube Manometer
Date	2021-02-18
Time	16:28
Vacuum Reading (in. w.c.)	-0.037
Number Vacuum Reading	-0.037

BV-1, 15:59, 25

Valve ID Link	34600 Beacon, BV-1
Valve ID	BV-1
Date	2021-02-18
Time	15:59
Valve Position at Arrival (% Open)	50
Valve Position at Departure (% Open)	25

BV-2, 15:59, 50

Valve ID Link	34600 Beacon, BV-2
Valve ID	BV-2
Date	2021-02-18
Time	15:59
Valve Position at Arrival (% Open)	50
Valve Position at Departure (% Open)	50
Were interim vacuum readings taken between initial and final vacuum readings?	No

Inspection Reading Analysis

Manometer

Is the system manometer steady?	Yes
SSMP/MPs	
Were any vacuum monitoring points not accessible? Please specify.	Unable to find other SSMP in garage.
Do all vacuum monitoring points meet -0.02 in w.c. threshold?	No
Which ones don't and why?	Both garage and basement have retrocoat
Proposed modifications to address vacuum?	none
Were any ball valve positions changed?	Yes
Did you take final readings?	Yes
Alarm Testing	
Sensaphone Link	N/A
Does the vacuum switch alarm work? Test the alarm condition and verify an alarm registers.	No
Does the fan disconnect alarm work? Test the alarm condition and verify an alarm registers.	Yes
Does the transmitter alarm work? Test the alarm condition and verify an alarm registers.	Yes
Check the alarm history on the disconnect for the fan. Was it off for any length of time?	No
Is the cloud logging vacuum readings properly (log in to check)?	Yes
Alarm Testing Comments	No vacuum switch at this location.
Repairs	
Sample Delay	
Send Sample Delay Email	N/A
email body	
Repair Completion	
Were seam repairs completed during this visit?	No
Were system repairs completed during this visit?	No
Are there outstanding repairs to be completed?	No
Owner/Tenant Observations	
Have there been any changes to the fan noise level or vibration?	No
Have any structures been built or modified that require vapor mitigation?	No
Engineer Notification	
Send Inspection Completion Email	N/A
email body	
Engineer Notification	

Send Inspection Completion Email - add any N/A repairs, repair needs, or critical communications in email text

email body

Created	2022-02-24 20:53:21 UTC by Seth Turner
Updated	2022-02-24 21:34:08 UTC by Seth Turner
General Information	
System Inspector	Seth Turner
Date	2022-02-24
Time	15:53
System Details Link	34600 Beacon
Property Address	34600 Beacon
Check Inspection(s) to be Completed	Full System Inspection
Get weather data from National Weather Service Website for your current location?	N/A
Weather	30F, cloudy
Ambient Temperature	30F
Barometric Pressure	29.93
Indoor Temperature	70
Design Components	
Does the house have a basement?	Yes
Does the house have a sump?	Yes
Does the house have garage retrocoat?	Yes
Does the house have shed retrocoat?	No
Does the house have basement retrocoat?	Yes
Does the house have a crawlspace barrier?	No
Does the house have an inaccessible crawlspace?	No
Does the house have a water sensor?	No
System Inspection	
Fan	
Fan(s) operating?	Yes
Are there any unusual fan noises?	No
Piping	
ls any caulking required around pipe penetrations, slab cracks, expansion joints, or foundation walls?	No
Are piping, piping joints, and brackets intact and secure?	Yes
s the insulation and insulation jacket damaged or missing in garage or exterior piping?	No
Valves	
Upon arrival, are all valves in the same position as	Yes

the prior visit (reference Power BI)?

Drains

Do any drain seals need to be repaired or replaced?	No		
Basement			
Is water present in the basement?	No		
Sumps			
Is the sump full/evidence pump is broken?	No		
Was the owner notified?	No		
Garage Retrocoat			
Is retrocoat damaged or missing?	No		
Basement Retrocoat			
Is retrocoat damaged or missing?	No		

Labels

Are labels present at the pipe, control panel, utube, and breaker?

Yes

Common Label Photos



Are labels present at the sump?

Yes

Sump Label Photos



Are labels present at the basement retrocoat?

Yes

Basement Retrocoat Label Photos





Vacuum Monitoring

Is the u-tube accurate (test with micromanometer/manometer, rezero/replace as needed)?	Yes
Is the vacuum switch accurate (test with micromanometer)?	Yes
Do any monitoring points (MP/SSMP) need to be repaired or replaced?	No
If multiple systems are present, were both inspected?	N/A

Inspection Measurements

Pre-Measurement Conditions

Are vacuum readings being taken under closed	Yes
building conditions?	
Do any monitoring points have transmitters?	No

Measurements and Valve Positions

U-Tube Manometer, 16:01, -0.078

Vacuum ID Link	34600 Beacon, U-Tube Manometer
Vacuum ID	U-Tube Manometer
Date	2022-02-24
Time	16:01
Vacuum Reading (in. w.c.)	-0.078

SSMP-2, 16:11, -0.

Vacuum ID Link	34600 Beacon, SSMP-2
Vacuum ID	SSMP-2
Date	2022-02-24
Time	16:11
Vacuum Reading (in. w.c.)	-0.004
Number Vacuum Reading	-0.004

BV-1, 16:11, 25

Valve ID Link	34600 Beacon, BV-1
Valve ID	BV-1
Date	2022-02-24
Time	16:11
Valve Position at Arrival (% Open)	25
Valve Position at Departure (% Open)	25

BV-2, 16:12, 50

34600 Beacon, BV-2
BV-2
2022-02-24
16:12
50
50
No

Inspection Reading Analysis

Manometer

SSMP/MPs

Were any vacuum monitoring points not accessible? Please specify.	No
Do all vacuum monitoring points meet -0.02 in w.c. threshold?	No
Which ones don't and why?	Retrocoat In garage and basement.
Proposed modifications to address vacuum?	None
Were any ball valve positions changed?	No

Alarm Testing

Sensaphone Link	N/A
Does the vacuum switch alarm work? Test the alarm condition and verify an alarm registers.	Yes

Does the fan disconnect alarm work? Test the alarm condition and verify an alarm registers.	Yes
Does the transmitter alarm work? Test the alarm condition and verify an alarm registers.	Yes
Check the alarm history on the disconnect for the fan. Was it off for any length of time?	No
Is the cloud logging vacuum readings properly (log in to check)?	Yes

Repairs

Sample Delay

Send Sample Delay Email	N/A
email body	

Repair Completion

Were seam repairs completed during this visit?	No
Were system repairs completed during this visit?	No
Are there outstanding repairs to be completed?	No

Owner/Tenant Observations

Have there been any changes to the fan noise level or vibration?	No
Have any structures been built or modified that require vapor mitigation?	No

Engineer Notification

Send Inspection Completion Email	N/A
email body	

Engineer Notification

Send Inspection Completion Email - add any repairs, repair needs, or critical communications in email text	N/A
email body	

Additional Notes and Photos

Photos











