# **Transmittal Letter**



**TO** Anthony Wallen 34920 Beacon Livonia, MI 48150

#### ELECTRONIC COPIES TO

Jeanne Schlaufman (EGLE) Todd Walton (Ford) Chuck Pinter (Ford)

PROJECT NUMBER 30146655 FROM Kristoffer Hinskey 248-994-2240 <u>kristoffer.hinskey@arcadis.com</u>

DATE October 4, 2022

**SUBJECT** Operation, Monitoring, and Maintenance Field Notes - 34920 Beacon

#### We are sending you:

Copies	Delivery Date	Description
1	10/6/2022	Operation, monitoring, and maintenance field notes.

#### Action\*

<ul> <li>A Approved</li> <li>AN Approved as Noted</li> <li>AS As Requested</li> <li>Other:</li></ul>	Correct and Resubmit File For Approval	Ret	ubmit Copies urn Copies view and Comment
Mailing Method			
<ul> <li>□ U.S. Postal Service 1<sup>st</sup> Class</li> <li>□ Certified/Registered Mail</li> <li>☑ Other: Email</li> </ul>	livery ☐ FedEx F rvice (UPS) ⊠ FedEx S	, 0	<ul> <li>FedEx 2-Day Delivery</li> <li>FedEx Economy</li> </ul>

#### **Comments:**

Attached are the interim preemptive mitigation (IPM) system Operation, Monitoring, and Maintenance (OM&M) field notes. These field notes were recorded during OM&M visits at the property between March 31, 2020 and March 31, 2022. Please let me know if you have any questions.

# 34920 Beacon, 2020-11-11, Full System Inspection

Created	2020-11-11 21:21:44 UTC by Seth Turner
Updated	2020-11-16 14:29:10 UTC by Seth Turner

## General Information

System Inspector	Seth Turner
Date	2020-11-11
Time	16:21
System Details Link	34920 Beacon
Property Address	34920 Beacon
Check Inspection(s) to be Completed	Full System Inspection
Get weather data from National Weather Service Website for your current location?	N/A
Weather	Mostly Clear
Ambient Temperature	46.04
Barometric Pressure	30.02
Indoor Temperature	70

# Design Components

Does the house have a basement?	No
Does the house have a sump?	No
Does the house have garage retrocoat?	Yes
Does the house have shed retrocoat?	No
Does the house have basement retrocoat?	No
Does the house have a crawlspace barrier?	Yes
Does the house have an inaccessible crawlspace?	Yes
Does the house have a water sensor?	No

# System Inspection


Fan			
Fan(s) operating?	Yes		
Are there any unusual fan noises?	No		
Piping			
Is any caulking required around pipe penetrations, slab cracks, expansion joints, or foundation walls?	No		
Are piping, piping joints, and brackets intact and secure?	Yes		
Is the insulation and insulation jacket damaged or missing in garage or exterior piping?	No		
Valves			
Upon arrival, are all valves in the same position as the prior visit (reference Power BI)?	Yes		

#### Drains

Do any drain seals need to be repaired or replaced?	No
Garage Retrocoat	
Is retrocoat damaged or missing?	No
Crawlspace Barrier	
Is water present on the vapor barrier?	No
Inaccessible Crawlspace	
Are all entry points, vents, cracks, or other opening crawlspaces being depressurized sealed?	Yes
Labels	

Are labels present at the pipe, control panel, u-Yes tube, and breaker?

Garage Retrocoat Label Photos




Are labels present at the garage retrocoat?	Yes
Are labels present at the crawlspace barrier?	Yes



Are labels present at the inaccessible crawlspace? Yes





ls the u-tube accurate (test with micromanometer/manometer, rezero/replace as needed)?	Yes
ls the vacuum switch accurate (test with micromanometer)?	Yes
Do any monitoring points (MP/SSMP) need to be repaired or replaced?	No
If multiple systems are present, were both inspected?	N/A

## Inspection Measurements

#### **Pre-Measurement Conditions**

Are vacuum readings being taken under closed building conditions?	Yes	
Do any monitoring points have transmitters?	No	

#### **Measurements and Valve Positions**

## MP-4, 16:29, -0.033

Vacuum ID Link	34920 Beacon, MP-4
Vacuum ID	MP-4
Date	2020-11-11
Time	16:29
Vacuum Reading (in. w.c.)	-0.033
Number Vacuum Reading	-0.033

## MP-2, 16:30, -0.030

Vacuum ID Link	34920 Beacon, MP-2
Vacuum ID	MP-2
Date	2020-11-11
Time	16:30
Vacuum Reading (in. w.c.)	-0.030
Number Vacuum Reading	-0.03

### MP-3, 16:30, -0.014

Vacuum ID Link	34920 Beacon, MP-3
Vacuum ID	MP-3
Date	2020-11-11
Time	16:30
Vacuum Reading (in. w.c.)	-0.014
Number Vacuum Reading	-0.014

## U-Tube Manometer, 16:31, -0.8

Vacuum ID Link	34920 Beacon, U-Tube Manometer
Vacuum ID	U-Tube Manometer
Date	2020-11-11
Time	16:31

Vacuum Reading (in. w.c.)	-0.8
Number Vacuum Reading	-0.8

## MP-1, 16:49, -0.020

Vacuum ID Link	34920 Beacon, MP-1
Vacuum ID	MP-1
Date	2020-11-11
Time	16:49
Vacuum Reading (in. w.c.)	-0.020
Number Vacuum Reading	-0.02

## BV-2, 16:36, 10

Valve ID Link	34920 Beacon, BV-2
Valve ID	BV-2
Date	2020-11-11
Time	16:36
Valve Position at Arrival (% Open)	10
Valve Position at Departure (% Open)	10

## BV-3, 16:37, 75

Valve ID Link	34920 Beacon, BV-3
Valve ID	BV-3
Date	2020-11-11
Time	16:37
Valve Position at Arrival (% Open)	75
Valve Position at Departure (% Open)	75

# BV-4, 16:38, 60

Valve ID Link	34920 Beacon, BV-4
Valve ID	BV-4
Date	2020-11-11
Time	16:38
Valve Position at Arrival (% Open)	60
Valve Position at Departure (% Open)	60

# BV-5, 16:39, 10

Valve ID Link	34920 Beacon, BV-5
Valve ID	BV-5
Date	2020-11-11
Time	16:39
Valve Position at Arrival (% Open)	10
Valve Position at Departure (% Open)	10

## BV-6, 16:39, 100

Valve ID Link	34920 Beacon, BV-6
Valve ID	BV-6

Date	2020-11-11
Time	16:39
Valve Position at Arrival (% Open)	100
Valve Position at Departure (% Open)	100

# BV-1, 16:50, 40

Valve ID Link	34920 Beacon, BV-1
Valve ID	BV-1
Date	2020-11-11
Time	16:50
Valve Position at Arrival (% Open)	40
Valve Position at Departure (% Open)	40
Were interim vacuum readings taken between initial and final vacuum readings?	No

# Inspection Reading Analysis

## Manometer

Is the system manometer steady?	Yes
SSMP/MPs	
Were any vacuum monitoring points not accessible? Please specify.	No
Do all vacuum monitoring points meet -0.02 in w.c. threshold?	No
Which ones don't and why?	MP-3
Proposed modifications to address vacuum?	Possible repairs
Were any ball valve positions changed?	No

# Alarm Testing

Sensaphone Link	N/A
Does the vacuum switch alarm work? Test the alarm condition and verify an alarm registers.	Yes
Does the fan disconnect alarm work? Test the alarm condition and verify an alarm registers.	Yes
Does the transmitter alarm work? Test the alarm condition and verify an alarm registers.	N/A
Check the alarm history on the disconnect for the fan. Was it off for any length of time?	No
Is the cloud logging vacuum readings properly (log in to check)?	N/A

# Repairs

Sample Delay		
Send Sample Delay Email	N/A	
email body		

## Repair Completion

No
No
Yes
Plan to return to increase vacuum influence.
No
No
N/A
N/A

## 34920 Beacon, 2020-11-17, System Check

Created	2020-11-17 18:11:42 UTC by Seth Turner
Updated	2020-11-17 19:49:09 UTC by Seth Turner

## General Information

System Inspector	Seth Turner
Date	2020-11-17
Time	13:11
System Details Link	34920 Beacon
Property Address	34920 Beacon
Check Inspection(s) to be Completed	System Check
Get weather data from National Weather Service Website for your current location?	N/A
Weather	Cloudy
Ambient Temperature	33.08
Barometric Pressure	30.26
Indoor Temperature	70

#### Inspection Measurements

#### **Pre-Measurement Conditions**

Are vacuum readings being taken under closed Yes building conditions?

#### **Measurements and Valve Positions**

#### MP-3, 13:22, -0.013

Vacuum ID Link	34920 Beacon, MP-3
Vacuum ID	MP-3
Date	2020-11-17
Time	13:22
Vacuum Reading (in. w.c.)	-0.013
Number Vacuum Reading	-0.013

#### MP-3, 14:04, -0.021

Vacuum ID Link	34920 Beacon, MP-3
Vacuum ID	MP-3
Date	2020-11-17
Time	14:04
Vacuum Reading (in. w.c.)	-0.021
Number Vacuum Reading	-0.021

#### MP-1, 14:04, -0.027

Vacuum ID Link	34920 Beacon, MP-1
Vacuum ID	MP-1
Date	2020-11-17
Time	14:04

Vacuum Reading (in. w.c.)	-0.027
Number Vacuum Reading	-0.027

## MP-2, 14:04, -0.034

Vacuum ID Link	34920 Beacon, MP-2
Vacuum ID	MP-2
Date	2020-11-17
Time	14:04
Vacuum Reading (in. w.c.)	-0.034
Number Vacuum Reading	-0.034

## MP-4, 14:04, -0.035

Vacuum ID Link	34920 Beacon, MP-4
Vacuum ID	MP-4
Date	2020-11-17
Time	14:04
Vacuum Reading (in. w.c.)	-0.035
Number Vacuum Reading	-0.035

## U-Tube Manometer, 14:05, -1.0

Vacuum ID Link	34920 Beacon, U-Tube Manometer
Vacuum ID	U-Tube Manometer
Date	2020-11-17
Time	14:05
Vacuum Reading (in. w.c.)	-1.0
Number Vacuum Reading	-1.0

## MP-3, 14:43, -0.025

Vacuum ID Link	34920 Beacon, MP-3
Vacuum ID	MP-3
Date	2020-11-17
Time	14:43
Vacuum Reading (in. w.c.)	-0.025
Number Vacuum Reading	-0.025

## MP-2, 14:44, -0.023

Vacuum ID Link	34920 Beacon, MP-2
Vacuum ID	MP-2
Date	2020-11-17
Time	14:44
Vacuum Reading (in. w.c.)	-0.023
Number Vacuum Reading	-0.023

MP-4, 14:44, -0.033		
Vacuum ID Link	34920 Beacon, MP-4	
Vacuum ID	MP-4	

Date	2020-11-17
Time	14:44
Vacuum Reading (in. w.c.)	-0.033
Number Vacuum Reading	-0.033

## MP-1, 14:46, -0.028

34920 Beacon, MP-1
MP-1
2020-11-17
14:46
-0.028
-0.028

# U-Tube Manometer, 14:47, -1.1

Vacuum ID Link	34920 Beacon, U-Tube Manometer
Vacuum ID	U-Tube Manometer
Date	2020-11-17
Time	14:47
Vacuum Reading (in. w.c.)	-1.1
Number Vacuum Reading	-1.1

## BV-3, 14:03, 15

Valve ID Link	34920 Beacon, BV-3
Valve ID	BV-3
Date	2020-11-17
Time	14:03
Valve Position at Departure (% Open)	15

# BV-2, 14:05, 10

Valve ID Link	34920 Beacon, BV-2
Valve ID	BV-2
Date	2020-11-17
Time	14:05
Valve Position at Departure (% Open)	10

## BV-1, 14:05, 40

Valve ID Link	34920 Beacon, BV-1
Valve ID	BV-1
Date	2020-11-17
Time	14:05
Valve Position at Departure (% Open)	40

## BV-6, 14:08, 100

Valve ID Link	34920 Beacon, BV-6
Valve ID	BV-6
Date	2020-11-17

Time	14:08
Valve Position at Departure (% Open)	100

# BV-5, 14:08, 10

Valve ID Link	34920 Beacon, BV-5
Valve ID	BV-5
Date	2020-11-17
Time	14:08
Valve Position at Departure (% Open)	10

## BV-4, 14:08, 50

Valve ID Link	34920 Beacon, BV-4
Valve ID	BV-4
Date	2020-11-17
Time	14:08
Valve Position at Departure (% Open)	50
Were interim vacuum readings taken between initial and final vacuum readings?	No

# Inspection Reading Analysis

## Manometer

Is the system manometer steady?	Yes	
---------------------------------	-----	--

### SSMP/MPs

Were any vacuum monitoring points not accessible? Please specify.	No
Do all vacuum monitoring points meet -0.02 in w.c. threshold?	Yes
Were any ball valve positions changed?	No

## Alarm Testing

0	
Sensaphone Link	N/A
Repairs	
Sample Delay	
Send Sample Delay Email	N/A
email body	
Repair Completion	
Were seam repairs completed during this visit?	Yes
Were system repairs completed during this visit?	No
Additional sealing completed:	Taped and sealed seams
Sealing Completion Date	2020-11-17
Caalina Danain Dhataa	

Sealing Repair Photos











Are there outstanding repairs to be completed?	No
Engineer Notification	
Send Inspection Completion Email	N/A
email body	
Engineer Notification	
	N/A

# 34920 Beacon, 2021-02-15, Full System Inspection

Created	2021-02-15 20:31:05 UTC by Seth Turner
Updated	2021-02-15 22:19:21 UTC by Seth Turner

## General Information

System Inspector	Seth Turner
Date	2021-02-15
Time	16:30
System Details Link	34920 Beacon
Property Address	34920 Beacon
Check Inspection(s) to be Completed	Full System Inspection
Get weather data from National Weather Service Website for your current location?	N/A
Weather	15F, cloudy
Ambient Temperature	15F
Barometric Pressure	30.03
Indoor Temperature	70

## **Design Components**

<u> </u>	
Does the house have a basement?	No
Does the house have a sump?	No
Does the house have garage retrocoat?	Yes
Does the house have shed retrocoat?	No
Does the house have basement retrocoat?	No
Does the house have a crawlspace barrier?	Yes
Does the house have an inaccessible crawlspace?	No
Does the house have a water sensor?	No

# System Inspection

Yes	
No	
No	
Yes	
No	
Yes	
	No No Yes No Yes

#### Drains

Do any drain seals need to be repaired or replaced?	No
Garage Retrocoat	
Is retrocoat damaged or missing?	No
Crawlspace Barrier	
ls water present on the vapor barrier?	No
Labels	
Are labels present at the pipe, control panel, u- tube, and breaker?	Yes
Common Label Photos	<section-header><text><text><text></text></text></text></section-header>

**B**Å**G** 

COOLING CO.

#### Are labels present at the garage retrocoat?

Yes

Garage Retrocoat Label Photos



Are labels present at the crawlspace barrier?

Barrier Label Photos



ls the u-tube accurate (test with micromanometer/manometer, rezero/replace as needed)?	Yes
ls the vacuum switch accurate (test with micromanometer)?	Yes
Do any monitoring points (MP/SSMP) need to be repaired or replaced?	No
lf multiple systems are present, were both inspected?	N/A

## **Inspection Measurements**

#### **Pre-Measurement Conditions**

Are vacuum readings being taken under closed building conditions?	Yes
Do any monitoring points have transmitters?	No

#### **Measurements and Valve Positions**

## MP-4, 16:32, -0.029

Vacuum ID Link	34920 Beacon, MP-4	
Vacuum ID	MP-4	
Date	2021-02-15	
Time	16:32	
Vacuum Reading (in. w.c.)	-0.029	
Number Vacuum Reading	-0.029	

## MP-2, 16:33, -0.020

Vacuum ID Link	34920 Beacon, MP-2
Vacuum ID	MP-2
Date	2021-02-15
Time	16:33
Vacuum Reading (in. w.c.)	-0.020
Number Vacuum Reading	-0.02

#### MP-3, 16:36, -0.020

34920 Beacon, MP-3
MP-3
2021-02-15
16:36
-0.020
-0.02

## MP-1, 16:42, -0.025

Vacuum ID Link	34920 Beacon, MP-1
Vacuum ID	MP-1
Date	2021-02-15
Time	16:42

Vacuum Reading (in. w.c.)	-0.025
Number Vacuum Reading	-0.025

# U-Tube Manometer, 16:42, -1.0

Vacuum ID Link	34920 Beacon, U-Tube Manometer
Vacuum ID	U-Tube Manometer
Date	2021-02-15
Time	16:42
Vacuum Reading (in. w.c.)	-1.0
Number Vacuum Reading	-1.0

## MP-2, 17:06, -0.024

Vacuum ID Link	34920 Beacon, MP-2
Vacuum ID	MP-2
Date	2021-02-15
Time	17:06
Vacuum Reading (in. w.c.)	-0.024
Number Vacuum Reading	-0.024

## MP-3, 17:07, -0.021

Vacuum ID Link	34920 Beacon, MP-3
Vacuum ID	MP-3
Date	2021-02-15
Time	17:07
Vacuum Reading (in. w.c.)	-0.021
Number Vacuum Reading	-0.021

## MP-4, 17:07, -0.032

Vacuum ID Link	34920 Beacon, MP-4
Vacuum ID	MP-4
Date	2021-02-15
Time	17:07
Vacuum Reading (in. w.c.)	-0.032
Number Vacuum Reading	-0.032

## U-Tube Manometer, 17:07, -1.1

34920 Beacon, U-Tube Manometer
U-Tube Manometer
2021-02-15
17:07
-1.1
-1.1

MP-1, 17:08, -0.026		
Vacuum ID Link	34920 Beacon, MP-1	
Vacuum ID MP-1		

Date	2021-02-15
Time	17:08
Vacuum Reading (in. w.c.)	-0.026
Number Vacuum Reading	-0.026

## BV-3, 16:38, 15

34920 Beacon, BV-3	
BV-3	
2021-02-15	
16:38	
15	
15	
-	

# BV-2, 16:38, 10

Valve ID Link	34920 Beacon, BV-2	
Valve ID	BV-2	
Date	2021-02-15	
Time	16:38	
Valve Position at Arrival (% Open)	10	
Valve Position at Departure (% Open)	10	

## BV-1, 16:38, 40

Valve ID Link	34920 Beacon, BV-1
Valve ID	BV-1
Date	2021-02-15
Time	16:38
Valve Position at Arrival (% Open)	40
Valve Position at Departure (% Open)	40

## BV-6, 16:38, 100

Valve ID Link	34920 Beacon, BV-6	
Valve ID	BV-6	
Date	2021-02-15	
Time	16:38	
Valve Position at Arrival (% Open)	100	
Valve Position at Departure (% Open)	100	

## BV-5, 16:38, 10

Valve ID Link	34920 Beacon, BV-5
Valve ID	BV-5
Date	2021-02-15
Time	16:38
Valve Position at Arrival (% Open)	10
Valve Position at Departure (% Open)	10

## BV-4, 16:38, 50

BV-4
2021-02-15
16:38
50
50
No
Yes

## SSMP/MPs

Were any vacuum monitoring points not accessible? Please specify.	NA
Do all vacuum monitoring points meet -0.02 in w.c. threshold?	Yes
Were any ball valve positions changed?	No

## Alarm Testing

Sensaphone Link	N/A
Does the vacuum switch alarm work? Test the alarm condition and verify an alarm registers.	Yes
Does the fan disconnect alarm work? Test the alarm condition and verify an alarm registers.	Yes
Does the transmitter alarm work? Test the alarm condition and verify an alarm registers.	N/A
Check the alarm history on the disconnect for the fan. Was it off for any length of time?	No
Is the cloud logging vacuum readings properly (log in to check)?	N/A

## Repairs

# Sample Delay

Sample Belay	
Send Sample Delay Email	N/A
email body	
Repair Completion	
Were seam repairs completed during this visit?	Yes
Were system repairs completed during this visit?	No
Additional sealing completed:	Taping of seams
Sealing Completion Date	2021-02-15



Are there outstanding repairs to be completed?	No
Owner/Tenant Observations	
Have there been any changes to the fan noise level or vibration?	No
Have any structures been built or modified that require vapor mitigation?	No
Engineer Notification	
Send Inspection Completion Email	N/A
email body	
Engineer Notification	
Send Inspection Completion Email - add any repairs, repair needs, or critical communications in email text	N/A
email body	
Additional Notes and Photos	

Photos



# 34920 Beacon, 2022-01-25, Full System Inspection

Created	2022-01-25 20:59:36 UTC by Seth Turner
Updated	2022-01-25 22:21:11 UTC by Seth Turner

## General Information

System Inspector	Seth Turner	
Date	2022-01-25	
Time	16:30	
System Details Link	34920 Beacon	
Property Address	34920 Beacon	
Check Inspection(s) to be Completed	Full System Inspection	
Get weather data from National Weather Service Website for your current location?	N/A	
Weather	23F, cloudy	
Ambient Temperature	23	
Barometric Pressure	29.92	
Indoor Temperature	70	

# Design Components

<u> </u>	
Does the house have a basement?	No
Does the house have a sump?	No
Does the house have garage retrocoat?	Yes
Does the house have shed retrocoat?	No
Does the house have basement retrocoat?	No
Does the house have a crawlspace barrier?	Yes
Does the house have an inaccessible crawlspace?	No
Does the house have a water sensor?	No

# System Inspection

Fan	
Fan(s) operating?	Yes
Are there any unusual fan noises?	No
Piping	
ls any caulking required around pipe penetrations, slab cracks, expansion joints, or foundation walls?	No
Are piping, piping joints, and brackets intact and secure?	Yes
Is the insulation and insulation jacket damaged or missing in garage or exterior piping?	No
Valves	
Upon arrival, are all valves in the same position as the prior visit (reference Power Bl)?	Yes

#### Drains

Do any drain seals need to be repaired or replaced?	No
Garage Retrocoat	
ls retrocoat damaged or missing?	No
Crawlspace Barrier	
Is water present on the vapor barrier?	No
Labels	
Are labels present at the pipe, control panel, u- tube, and breaker?	Yes
Common Label Photos	

Are labels present at the garage retrocoat?

Yes

Garage Retrocoat Label Photos



Are labels present at the crawlspace barrier?

Barrier Label Photos



ls the u-tube accurate (test with micromanometer/manometer, rezero/replace as needed)?	Yes
ls the vacuum switch accurate (test with micromanometer)?	Yes
Do any monitoring points (MP/SSMP) need to be repaired or replaced?	No
If multiple systems are present, were both inspected?	N/A

## Inspection Measurements

#### **Pre-Measurement Conditions**

Are vacuum readings being taken under closed building conditions?	Yes
Do any monitoring points have transmitters?	No

#### **Measurements and Valve Positions**

## U-Tube Manometer, 16:31, -1.0

Vacuum ID Link	34920 Beacon, U-Tube Manometer
Vacuum ID	U-Tube Manometer
Date	2022-01-25
Time	16:31
Vacuum Reading (in. w.c.)	-1.0
Number Vacuum Reading	-1.0

## MP-3, 16:33, -0.022

Vacuum ID Link	34920 Beacon, MP-3
Vacuum ID	MP-3
Date	2022-01-25
Time	16:33
Vacuum Reading (in. w.c.)	-0.022
Number Vacuum Reading	-0.022

### MP-2, 16:33, -0.023

## MP-4, 16:34, -0.030

Vacuum ID Link	34920 Beacon, MP-4
Vacuum ID	MP-4
Date	2022-01-25
Time	16:34

Vacuum Reading (in. w.c.)	-0.030
Number Vacuum Reading	-0.03

## MP-1, 16:36, -0.027

Vacuum ID Link	34920 Beacon, MP-1
Vacuum ID	MP-1
Date	2022-01-25
Time	16:36
Vacuum Reading (in. w.c.)	-0.027
Number Vacuum Reading	-0.027

## U-Tube Manometer, 16:48, -1.2

Vacuum ID Link	34920 Beacon, U-Tube Manometer
Vacuum ID	U-Tube Manometer
Date	2022-01-25
Time	16:48
Vacuum Reading (in. w.c.)	-1.2
Number Vacuum Reading	-1.2

#### MP-3, 16:48, -0.022

Vacuum ID Link	34920 Beacon, MP-3
Vacuum ID	MP-3
Date	2022-01-25
Time	16:48
Vacuum Reading (in. w.c.)	-0.022
Number Vacuum Reading	-0.022

## MP-2, 16:48, -0.023

Vacuum ID Link	34920 Beacon, MP-2
Vacuum ID	MP-2
Date	2022-01-25
Time	16:48
Vacuum Reading (in. w.c.)	-0.023
Number Vacuum Reading	-0.023

## MP-4, 16:48, -0.031

Vacuum ID Link	34920 Beacon, MP-4
Vacuum ID	MP-4
Date	2022-01-25
Time	16:48
Vacuum Reading (in. w.c.)	-0.031
Number Vacuum Reading	-0.031

MP-1, 16:49, -0.027		
Vacuum ID Link	34920 Beacon, MP-1	
Vacuum ID	MP-1	

Date	2022-01-25
Time	16:49
Vacuum Reading (in. w.c.)	-0.027
Number Vacuum Reading	-0.027

## MP-3, 17:18, -0.023

Vacuum ID Link	34920 Beacon, MP-3
Vacuum ID	MP-3
Date	2022-01-25
Time	17:18
Vacuum Reading (in. w.c.)	-0.023
Number Vacuum Reading	-0.023

## MP-1, 17:18, -0.027

Vacuum ID Link	34920 Beacon, MP-1
Vacuum ID	MP-1
Date	2022-01-25
Time	17:18
Vacuum Reading (in. w.c.)	-0.027
Number Vacuum Reading	-0.027

## MP-4, 17:18, -0.031

Vacuum ID Link	34920 Beacon, MP-4
Vacuum ID	MP-4
Date	2022-01-25
Time	17:18
Vacuum Reading (in. w.c.)	-0.031
Number Vacuum Reading	-0.031

#### MP-2, 17:18, -0.023

Vacuum ID Link	34920 Beacon, MP-2
Vacuum ID	MP-2
Date	2022-01-25
Time	17:18
Vacuum Reading (in. w.c.)	-0.023
Number Vacuum Reading	-0.023

## U-Tube Manometer, 17:18, -1.2

Vacuum ID Link	34920 Beacon, U-Tube Manometer
Vacuum ID	U-Tube Manometer
Date	2022-01-25
Time	17:18
Vacuum Reading (in. w.c.)	-1.2
Number Vacuum Reading	-1.2

## BV-1, 16:43, 40

Valve ID Link	34920 Beacon, BV-1
Valve ID	BV-1
Date	2022-01-25
Time	16:43
Valve Position at Arrival (% Open)	40
Valve Position at Departure (% Open)	40

# BV-2, 16:43, 10

Valve ID Link	34920 Beacon, BV-2
Valve ID	BV-2
Date	2022-01-25
Time	16:43
Valve Position at Arrival (% Open)	10
Valve Position at Departure (% Open)	10

## BV-3, 16:44, 15

Valve ID Link	34920 Beacon, BV-3		
Valve ID	BV-3		
Date	2022-01-25		
Time	16:44		
Valve Position at Arrival (% Open)	15		
Valve Position at Departure (% Open)	15		

## BV-4, 16:44, 50

Valve ID Link	34920 Beacon, BV-4		
Valve ID	BV-4		
Date	2022-01-25		
Time	16:44		
Valve Position at Arrival (% Open)	50		
Valve Position at Departure (% Open)	50		

# BV-5, 16:44, 10

Valve ID Link	34920 Beacon, BV-5		
Valve ID	BV-5		
Date	2022-01-25		
Time	16:44		
Valve Position at Arrival (% Open)	10		
Valve Position at Departure (% Open)	10		

## BV-6, 16:44, 100

Valve ID Link	34920 Beacon, BV-6		
Valve ID	BV-6		
Date	2022-01-25		
Time	16:44		
Valve Position at Arrival (% Open)	100		
Valve Position at Departure (% Open)	100		

# Inspection Reading Analysis

#### Manometer

Is the system manometer steady?	Yes
SSMP/MPs	
Were any vacuum monitoring points not accessible? Please specify.	No
Do all vacuum monitoring points meet -0.02 in w.c. threshold?	Yes
Were any ball valve positions changed?	No

## Alarm Testing

Sensaphone Link	N/A
Does the vacuum switch alarm work? Test the alarm condition and verify an alarm registers.	Yes
Does the fan disconnect alarm work? Test the alarm condition and verify an alarm registers.	Yes
Does the transmitter alarm work? Test the alarm condition and verify an alarm registers.	N/A
Check the alarm history on the disconnect for the fan. Was it off for any length of time?	No
Is the cloud logging vacuum readings properly (log in to check)?	N/A

## Repairs

#### Sample Delay

Send Sample Delay Email	N/A		
email body			

## **Repair Completion**

• •	
Were seam repairs completed during this visit?	Yes
Were system repairs completed during this visit?	No
Additional sealing completed:	Tape repairs by MP-3. Sikaflex applied above batten bar on west side of crawlspace.
Sealing Completion Date	2022-01-25

Sealing Repair Photos







Are there outstanding repairs to be completed? No

Have there been any changes to the fan noise level or vibration?	No
Have any structures been built or modified that require vapor mitigation?	No
Engineer Notification	
Send Inspection Completion Email	N/A
email body	
Engineer Notification	
Send Inspection Completion Email - add any repairs, repair needs, or critical communications in email text	N/A
email body	